

Step 1:


Begin the assembly process by placing each component individually into the ultrasonic welding machine. Ensure that all parts are correctly positioned to guarantee precise welding and secure bonding.

*These 7 parts go in a single block.


Step 2:

All necessary parts for the motor assembly are shown here. At this stage, adhesives and specialized tools are used to aid in the assembly process.


Note: For a detailed demonstration of the entire process, please refer to the full instructional video.



*These 17 parts go in a single block.



*These 3 parts go in a single block.



COMPLETE ASSEMBLY

